Date: 12/07/2022 3:26:18 PM From: sch4p4(6) Persor To: "Neville Atkinson"

Cc: sch4p4(6) Pe, "sch4p4(6) Cfmeuqld.asn.au", sch4p4(6) Personal information

s.73 Irrelevant inform sch4p4(6) Persor

sch4p4(, "Grosvenor Mine Record"

Subject: 20220710 - HPI - CMW Pinned with LHD Against Pump - 1A Notification

Attachment: 220710 HPI CMW Pinned with LHD Against Pump -

1A.pdf;image001.png;image002.png;image003.png;image004.png;image005.png;image006.png;image007.png;

[OFFICIAL]

Good Afternoon Mr Atkinson,

Please find attached, sent on behalf of SSE, s.73 Irrelevan notification for an incident that occurred at Grosvenor Mine on the 10/07/2022.

Kind Regards,

sch4p4(6) Pers Executive Assistant to:

s.73 Irrelevan

General Manager and Site Senior Executive



Esch4p4(6) angloamerican.com Sch4p4(6) Persor GROSVENOR MINE

464 Goonyella Road, Moranbah, QLD, 4744, Australia T+61 7 4985 0200 www.angloamerican.com

A member of the Anglo American plc group







CONFIDENTIALITY CAUTION: This email (including any attachments) is intended only for the use of the individual or entity to whom it is addressed and may contain confidential information and be protected by legal privilege. Rease notify us immediately by return email if you have received this email in error and delete this email and any attachments. If you are not the intended recipient, dissemination, disclosure and use of any information herein is prohibited. PRIVACY NOTICE Anglo American processes personal data in accordance with applicable data privacy laws. For more information please see our Privacy Policy. Published on F

Date: 10/07/2022 3:33:55 PM From: Sch4p4(6) Personal info

To: "Neville Atkinson", "Jason Hill"

Subject: Crush Injury to CMW

Attachment: 220710 HPI CMW Pinned with LHD Against

Pump.docx;image001.jpg;image002.jpg;image003.jpg;image004.jpg;image005.jpg;image006.jpg;image007.jpg;

[OFFICIAL]

Neville/Jason

Please find attached a draft copy if the Form 1A for the serious accident that occurred today at Grosvenor. I have included a plan of the incident scene and will send a final version when we get the photographs etc of the incident

Regards

sch4p4(6) Person Underground Mne Manager Grosvenor



COAL

GROSVENOR MINE

464 Goonyella Rd, Moranbah, 4744

Australia

www.angloamerican.com.au

A member of the Anglo American plc group



CONFIDENTIALITY CAUTION: This email (including any attachments) is intended only for the use of the individual or entity to whomit is addressed and may contain confidential information and be protected by legal privilege. Rease notify us immediately by return email if you have received this email in error and delete this email and any attachments. If you are not the intended recipient, disclosure and use of any information herein is prohibited. PRIVACY NOTICE Anglo American processes personal data in accordance with applicable data privacy laws. For more information please see our Privacy Policy.

Date: 25/09/2022 8:15:00 PM

From: "Stephen Smith (Mining Inspector)"

To: sch4p4(6) Personal in

Subject: No Go zone HPI 10 July 2022

Attachment: image001.png;

Hi sch4p

In the form 5A for this HPI, the preventative action is to investigate option of pumping concrete from the surface.

- Has the investigation reached a conclusion on this preventative action?
- Were any other preventative actions implemented to prevent a recurrence?

Thanks

Steve Smith

Stephen Smith

Regional Inspector of Coal Mines North Region Resources Safety & Health Queensland

